

BELLSOUTH

BellSouth Corporation
Suite 900
1133-21st Street, N.W.
Washington, D.C. 20036-3351

mary.henze@bellsouth.com

RECEIVED

DEC 12 2000

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY

Mary L. Henze
Executive Director
Federal Regulatory Affairs

202 463-4109
202 463-4631 Fax

December 11, 2000

Ms. Magalie R. Salas
Secretary
Federal Communications Commission
The Portals
445 Twelfth Street, S.W.
Washington, DC 20554

Re: BellSouth's Public Notices of Network Change Under Rule 51.329(a)
CC Docket No. 96-98

Dear Ms. Salas:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Public Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98.

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division.

Should you have any questions regarding this submission, please contact me at (202) 463-4109.

Sincerely,



Mary L. Henze
Executive Director - Federal Regulatory Affairs

Attachment

cc: L. Charles Keller (with diskette)
Carmell Weathers (with diskette)

No. of Copies rec'd 0+2
List ABCDE

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, June 23, 2001, at 12:01 AM Central Daylight Time.

Location of Changes: Cleveland, Mississippi

Description of Change Planned: Cleveland, Mississippi Central Office – The Siemens Stromberg-Carlson switch (CLEVMSMADS0) will be converted to a Lucent Technologies 5ESS switch. The new Common Language Location Identifier (CLLI) for this switch will be CLEVMSMADS2. The point code will remain 252-146-056. The following NXX codes will be affected by this conversion:

Area Code: 662 **NXX:** 843, 846, 721

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office, will need to transition these trunks to the new switch. In order to ensure a smooth transition, BellSouth will provide interconnecting carriers and service providers Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers or service providers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date. Additionally, a service order freeze will be in effect from Friday, June 15, 2001, through Sunday, June 24, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Wanda Sutphin, Manager - Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-0029
-----------------	--	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region:	AL, KY, LA, MS and TN	557-2647
	FL, GA, NC, and SC	780-2171
	(When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above)	
Outside the BellSouth region:	1-800-786-7619	
Fax:	(205) 321-2191	

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, July 7, 2001 at 12:01 AM Central Daylight Time

Location of Changes: Friars Point, Mississippi

Description of Change Planned: Friars Point, Mississippi Central Office - The Siemens Stromberg-Carlson switch (FRPNMSMADS1) will be converted to a Lucent Technologies 5ESS switch. The new Common Language Location Identifier (CLLI) for this switch will be FRPNMSMARS9, and the point code will be 252-146-022. The new switch will be a remote working from the Oxford Host (OXFRMSMADS0). The following NXX codes will be affected:

Area Code: 662 **NXX:** 383

Description of Reasonably Foreseeable Impact of the Planned Change: It will be necessary for carriers with existing trunk groups to this office to transition these trunks to the new switch. Additionally, a service order freeze will be in effect from Friday, June 29, 2001, through Sunday, July 8, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Deborah B. Davis, Manager - Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-2261
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region:	AL, KY, LA, MS and TN 557-2647 FL, GA, NC, and SC 780-2171 (When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above)
--------------------------	---

Outside the BellSouth region: Fax:	1-800-786-7619 (205) 321-2191
---------------------------------------	----------------------------------

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, June 23, 2001, at 12:01 AM Central Daylight

Location of Changes: McComb, Mississippi

Description of Change Planned: McComb, Mississippi Central Office – The Siemens Stromberg-Carlson DCO switch (MCCMMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be MCCMMSMARS9, and the new point code will be 252-146-019. The following NXX codes will be affected with this conversion: **Area Code:** 601 **NXX:** 249, 250, 684

Description of Reasonably Foreseeable Impact of the Planned Change: Issuance of service requests to disconnect existing trunk groups to this office will be necessary. Interconnecting carriers and service providers may elect to add trunks at the new host office, which will be the Brookhaven 5ESS (BRHNMSMADS0), to carry this traffic. In order to ensure a smooth transition, BellSouth will provide interconnecting carriers and service providers Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers or service providers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, June 15, 2001, through Sunday, June 24, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In BellSouth Region:	AL, KY, LA, MS and TN	557-2647
	FL, GA, NC, and SC	780-2171
	When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above	
Outside BellSouth region:	1-800-786-7619	
Fax:	(205) 321-2191	

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, July 28, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Philadelphia, Mississippi

Description of Change Planned: Philadelphia, Mississippi Central Office – The Siemens Stromberg-Carlson DCO switch (PHLAMSMADS0) will be converted to a Lucent Technologies 5ESS switch. The new Common Language Location Identifier (CLLI) for this switch will be PHLAMSMADS2. The point code will remain 252-146-081. The following NXX codes will be affected with this conversion:

Area Code: 601 **NXX:** 389,650,656,663

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office, will need to transition these trunks to the new switch. In order to ensure a smooth transition, BellSouth will provide interconnecting carriers and service providers Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers or service providers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, July 20, 2001, through Sunday, July 29, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region:	AL, KY, LA, MS and TN	557-2647
	FL, GA, NC, and SC	780-2171
	(When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above)	

Outside the BellSouth region:	1-800-786-7619
Fax:	(205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, September 8, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Quitman, Mississippi

Description of Change Planned: Quitman, Mississippi Central Office - The Nortel DMS-10 switch (QTMNMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be QTMNMSMARS9, and the new point code will be 252-146-089.

The following NXX codes will be affected with this conversion:

Area Code: 601	NXX 776
Area Code: 334	NXX 771

Description of Reasonably Foreseeable Impact of the Planned Change: Issuance of service requests to disconnect existing trunk groups to this office will be necessary. Interconnecting carriers and service providers may elect to add trunks at the new host office, which will be the Meridian 5ESS (MRDNMSTLDS0), to carry this traffic.

A service order freeze will be in effect from Friday, August 31, 2001, through Sunday, September 9, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region:	AL, KY, LA, MS and TN	557-2647
	FL, GA, NC, and SC	780-2171
	When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above)	
Outside the BellSouth region:	1-800-786-7619	
Fax:	(205) 321-2191	

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, July 14, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Shubuta, Mississippi

Description of Change Planned: Shubuta, Mississippi Central Office - The Nortel DMS-10 switch (SHBTMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be SHBTMSMARS9, and the new point code will be 252-146-089.

The following NXX codes will be affected with this conversion: **Area Code:** 601 **NXX** 687

Description of Reasonably Foreseeable Impact of the Planned Change: Issuance of service requests to disconnect existing trunk groups to this office may be necessary. Interconnecting carriers and service providers may elect to add trunks at the new host office, which will be the Meridian 5ESS (MRDNMSTLDS0), to carry this traffic.

Additionally, a service order freeze will be in effect from Friday, July 6, 2001, through Sunday, July 15, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region:	AL, KY, LA, MS and TN	557-2647
	FL, GA, NC, and SC	780-2171
	When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above)	

Outside the BellSouth region:	1-800-786-7619
Fax:	(205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, September 22, 2001- 12:01 AM Central Daylight Time

Location of Changes: Waynesboro, Mississippi

Description of Change Planned: Waynesboro, Mississippi Central Office - The Nortel DMS-10 switch (WYBOMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be WYBOMSMARS9, and the new point code will be 252-146-089. The following NXX codes will be affected with this conversion:

Area Code: 601 **NXX** 671 & 735

Description of Reasonably Foreseeable Impact of the Planned Change: Issuance of service requests to disconnect existing trunk groups to this office will be necessary. Interconnecting carriers and service providers may elect to add trunks at the new host office, which will be the Meridian 5ESS (MRDNMSTLDS0), to carry this traffic.

Additionally, a service order freeze will be in effect from Friday, September 14, 2001, through Sunday, September 23, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (IPC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region:	AL, KY, LA, MS and TN	557-2647
	FL, GA, NC, and SC	780-2171
	When calling from an area with 10-digit dialing, dial the area code and the appropriate 7-digit number shown above)	

Outside the BellSouth region:	1-800-786-7619
Fax:	(205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, October 6, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Buckatunna, Mississippi

Description of Change Planned: Buckatunna Mississippi Central Office Conversion: The Nortel DMS-10 switch (BCTNMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be BCTNMSMARS9, and the new point code will be 252-146-089. The new switch will be a remote working from the Meridian Host (MRDNMSTLDS0). The following NXX code will be affected with this conversion:

Area Code: 601 **NXX:** 648

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, September 28, 2001, through Sunday, October 7, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include
your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, August 11, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Dekalb, Mississippi

Description of Change Planned: Dekalb Mississippi Central Office Conversion - The Nortel DMS-10 switch (DKLBMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be DKLBMARS9, and the new point code will be 252-146-081. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADS2). The following NXX code will be affected with this conversion:

Area Code: 601 **NXX:** 743

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, August 3, 2001, through Sunday, August 12, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include
your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, August 18, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Enterprise, Mississippi

Description of Change Planned: Enterprise Mississippi Central Office Conversion – The Nortel DMS-10 switch (ENTRMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be ENTRMSMARS9, and the **new point code will be 252-146-089**. The new switch will be a remote working from the Meridian Host (MRDNMSTLDS0). The following NXX code will be affected with this conversion:

Area Code: 601 NXX 659

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSr. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSr Response Due Date.

A service order freeze will be in effect from Friday, August 10, 2001, through Sunday, August 19, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
 780-2171 (FL, GA, NC, SC)
 (If you are calling from a mandatory 10-digit calling area, include
 your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, October 20, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Louisville, Mississippi

Description of Change Planned: Louisville Mississippi Central Office Conversion - The Siemens Stromberg-Carlson RNS switch (LSVLMSMADS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be LSVLMSMARS9, and the new point code will be 252-146-081. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADS2). The following NXX code will be affected with this conversion: **Area Code:** 662 **NXX:** 773, 779

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office will need to transition these trunks to the new switch. Interconnecting carriers may elect to add trunks at the new host office, which will be the Philadelphia 5ESS (PHLAMSMADS2), to carry this traffic. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

A service order freeze will be in effect from Friday, October 12, 2001, through Sunday, October 21, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include
your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, August 25, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Union, Mississippi

Description of Change Planned: Union Mississippi Central Office Conversion - The Siemens Stromberg-Carlson RNS switch (UNINMSDSDS0) will be converted to a Lucent Technologies 5ESS EXM2000 remote switch. The new Common Language Location Identifier (CLLI) for this switch will be UNINMSDSRS9, and the new point code will be 252-146-081. The new switch will be a remote working from the Philadelphia Host (PHLAMSMADS2). The following NXX code will be affected with this conversion: **Area Code:** 601 **NXX:** 774

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office would need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSR. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSR Response Due Date.

Please note that a service order freeze will be in effect from Friday, August 17, 2001, through Sunday, August 26, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period

Contact:	Technical questions relating to this change should be directed to:	Lisa Secrest, Manager – Network 175 East Capitol Street, 580 LMC Jackson, Mississippi 39201 (601) 961-3242
-----------------	--	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include
your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Saturday, June 23, 2001, at 12:01 AM Central Daylight Time

Location of Changes: Citronelle, Alabama

Description of Change Planned: Citronelle Alabama Central Office Conversion - The DMS 10 switch CTRNALNMDS0 will be converted to a Lucent EXM-2000 and will be a remote of the Mobile Saraland (MOBLALSADS0) switch. The new Common Language Location Identifier (CLLI) for this switch will be CTRNALNMRS0 and the point code will be 252 143 006. The following NXX code will be affected with this conversion:

Area Code: 334 **NXX:** 866

Description of Reasonably Foreseeable Impact of the Planned Change: Interconnecting carriers with existing trunk groups to this end office will need to transition these trunks to the new switch. To help ensure a smooth transition, BellSouth will provide interconnecting carriers with Trunk Group Service Request Forms (TGSRs) that must be returned to BellSouth by the Response Due Date provided on the TGSRs. Interconnecting carriers planning to submit Access Service Requests (ASRs) should indicate their intent on the TGSRs that are returned to BellSouth and submit their ASRs by the TGSRs Response Due Date.

A service order freeze will be in effect Saturday, June 16 through Tuesday, June 26, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact: Technical questions relating to this change should be directed to:

Deborah Chenier Hughes
3196 Highway 280 South, Suite 110-N
Birmingham, AL 35243
(205) 972-2207

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: September 22, 2001, at approximately 2:00 AM Central Daylight Time

Location of Changes: Birmingham, Alabama

Description of Change Planned: Montgomery Main & Toll, Alabama Central Office Conversion - The 1AESS switch (MTGMALMT26E) will be replaced with a Lucent Technologies 5ESS. The new Common Language Location Identifier (CLLI) for the Montgomery Main & Toll switch will be MTGMALMTDS2 and the new point code will be 252-140-015. The following NXX codes will be affected by this conversion: **Area Code:** 334 **NXX:** 230, 236, 240, 241, 261, 262, 263, 264, 265, 269, 293, 516, 517, 519, 547, 570, 571, 832, 834, 851, 860.

Description of Reasonably Foreseeable Impact of the Planned Change: It will be necessary for carriers with existing trunk groups to this office to transition these trunks to the new switch. In order to ensure a smooth transition, BellSouth will provide Trunk Group Service Requests Forms (TGSRs) that must be returned to BellSouth. In addition, if a carrier or service provider plans to submit Access Service Requests (ASRs), they should indicate their intent on the TGSRs that are returned to BellSouth.

A service order freeze will be in effect from Friday, September 14, 2001, through Monday, September 24, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lura J. Campbell, Manager – Network 3196 Highway 280 Room 107NA Birmingham, Alabama 35243 (205) 972-2773
-----------------	--	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191

NOTICE OF NETWORK CHANGE UNDER RULE 51.329(a)

Date: December 11, 2000

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: August 25, 2001, at approximately 2:00 AM Central Daylight Time

Location of Changes: Birmingham, Alabama

Description of Change Planned: Birmingham Valley, Alabama Central Office Conversion - The 1AESS switch (BRHMALVA82E) will be replaced with a Lucent Technologies 5ESS. The new Common Language Location Identifier (CLLI) for the Birmingham Valley switch will be BRHMALVADS0 and the new point code will be 252-134-062. The following NXX codes will be affected by this conversion:

Area Code: 205 **NXX:** 267, 822, 823, 824, 978, 979.

Description of Reasonably Foreseeable Impact of the Planned Change: It will be necessary for carriers with existing trunk groups to this office to transition these trunks to the new switch. In order to ensure a smooth transition, BellSouth will provide Trunk Group Service Requests Forms (TGSRs) that must be returned to BellSouth. In addition, if a carrier or service provider plans to submit Access Service Requests (ASRs), they should indicate their intent on the TGSRs that are returned to BellSouth.

A service order freeze will be in effect from Friday, August 18, 2001, through Monday, August 27, 2001. Therefore, scheduling Point of Presence (POP) moves, major trunking rearrangements, translation changes, or critical dates should be avoided during this period.

Contact:	Technical questions relating to this change should be directed to:	Lura J. Campbell, Manager – Network 3196 Highway 280 Room 107NA Birmingham, Alabama 35243 (205) 972-2773
-----------------	--	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Switching Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth Region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area, include your local area code.)

Outside BellSouth Region: 1-800-786-7619
Fax: (205) 321-2191